



Bulletin No.: PIT6246

Published date: N/A

Preliminary Information

PIT6246 AM Radio Inoperative

Proactive

Models

Brand: Model: Model Years: VIN: Engine: Transmissions:
from to

Buick Envision 2024 All All All All

| | |
|-----------------------------------|---|
| Involved Region or Country | United States, Canada, Mexico |
| Additional Options (RPO) | IVE |
| Condition | Some customers may comment that their AM radio does not work. |
| Cause | This maybe due to a software anomaly. |

Correction:

GM is aware of this issue and will provide an update though a service bulletin when a fix becomes available.

Please do not replace any parts at this time.


Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor Operation | Description | Labor Time |
|--|--------------------------------|------------|
| 3486288 | Verify AM Radio Is Inoperative | 0.2 Hr. |
| *This is a unique Labor Operation for Bulletin use only. | | |

Version History

| | |
|-----------------|--------------------------|
| Version | 1 |
| Modified | 10/01/2024 - Created On. |

 GM Global Brands

© 2024 General Motors. All Rights Reserved.