



Bulletin No.: PIT6221A

Published date: 10/3/2024

Preliminary Information

PIT6221A Steering Wheel Oscillates or Vibrates in Super Cruise Mode

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Enclave	2025	All	All All	All
Chevrolet	Traverse (all new)	2024	All	All LK0	All
Chevrolet	Traverse	2025	All	All All	All
GMC	Acadia	2024 - 2025	All	All All	All

Involved Region or Country	North America
Additional Options (RPO)	UKL
Condition	Steering wheel vibrating, dithering, or oscillating while driving. This condition will only be experienced when driving with super cruise activated. If this condition is experienced with super cruise turned off this PI does not apply.
Cause	Software

Correction:

Do not perform any repairs at this time.

Engineering is working on updated software.

When software for this concern becomes available a bulletin will be released.

Version History

Version	2
Modified	08/20/2024 - Created on. 10/03/2024 - Updated correction.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.