



Bulletin No.: PIT6252

Published date: N/A

Preliminary Information

PIT6252 Wireless Android Auto Inoperative

Proactive

Models

Brand: Model: Model Years: VIN: Engine: Transmissions:
from to

Buick Envision 2024 All All All All

Involved Region or Country	Canada
Additional Options (RPO)	IVE
Condition	Some customers may comment that their wireless Android Auto does not work. While wired Android Auto and wired/wireless Apple Carplay still functions.
Cause	This maybe due to a software anomaly.

Correction:

GM is aware of this issue and will provide an update through a service bulletin when a fix becomes available.

Please do not replace any parts at this time.


Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3486308	Verify Wireless Android Auto Is Inop	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	10/04/2024 - Created On.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.