



Bulletin No.: PIC6577

Published date: 10/14/2024

Preliminary Information

PIC6577 Front Compartment Exterior Touchpad May Require a Second Activation

Models

Brand: **Model:** **Model Years:** **VIN:** **Engine:** **Transmissions:**
from to

Chevrolet Corvette 2025 All All All All

Involved Region or Country	North America
Condition	Some customers may comment that the front compartment lid will not open after pressing the exterior release switch that is located under the left front headlamp. The customer may notice that the exterior lamps may flash, but the front compartment lid did not release as expected. After a few seconds, a subsequent press of the exterior touchpad releases the front compartment lid correctly. Opening the front compartment lid using the key fob or the interior release switch located on the driver's door is unaffected.
Concern	This concern is caused by an initialization issue between the control modules used in this system when the car is fully asleep. The messages may not be transmitted properly.

Correction:

If you encounter a vehicle with this concern, please do not replace any parts on the vehicle. GM engineering is aware of this issue and they are currently developing a software solution for this concern. When new software is available, an update will be provided.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
0541709	Body System Electronics - Customer Concern Not Duplicated - CCND	0.3 hours

Version History

Version	1
Modified	10/14/2024 - Created on.

GM Global Brands

© 2024 General Motors. All Rights Reserved.