



Bulletin No.: PIT6260

Published date: 10/18/2024

Preliminary Information

PIT6260 Dead Battery / Excessive Battery Draw Drain Parasitic / Low Battery Voltage / Reprogram BCM

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Cadillac	Escalade Models	2022 - 2024	All All	All	All
Chevrolet	Suburban	2022 - 2024	All All	All	All
Chevrolet	Tahoe	2022 - 2024	All All	All	All
GMC	Yukon Models	2022 - 2024	All All	All	All

Involved Region or Country	North America
Condition	<p>Some customers may comment of a no crank due to a low or dead battery. This battery draw condition is more likely to occur if the vehicle is left unlocked and/or the key fob is left inside the vehicle.</p> <p>NOTE: This condition was previously reported in bulletins: 24-NA-039 and PIT5973.</p>
Cause	BCM software anomaly

Correction:

To correct this concern reprogram the K9 BCM with the latest calibrations in TLC/SPS.


Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Time

Version History

Version	1
Modified	10/18/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.