



Bulletin No.: PIT6263

Published date: N/A

Preliminary Information

PIT6263 Diagnostic Tip for Battery Issues - Intermittent No Crank - No Start - Stall - Check Engine Light

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore GX	2024 - 2025	All	All	All	All
Buick	Envista	2024 - 2025	All	All	All	All
Chevrolet	Trailblazer	2024 - 2025	All	All	All	All
Chevrolet	Trax	2024 - 2025	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment that the vehicle has intermittently stalled while driving or has an intermittent no crank no start condition.
Cause	Battery maintenance (battery disconnect) may have been performed at intermediate ports due to long stand time.

Correction:

Check for a loose negative battery terminal and tighten as needed.

Version History

Version	1
Modified	10/22/2024 - Created.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.