



**Bulletin No.:** PIT6068C

**Published date:** N/A

## Preliminary Information

### PIT6068C Service Driver Assist B1A05

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN:</b> from to	<b>Engine:</b>	<b>Transmissions:</b>
Cadillac	LYRIQ	2024 - 2025	All	All All	All
Chevrolet	Blazer EV	2024 - 2025	All	All All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	<b>Service driver assist message. On inspection B1A05 will be found in the B174W Front View Camera Module (FVCM).</b>
<b>Cause</b>	<b>Software</b>

#### Correction:

**Reprogram B174W FVCM using SPS.**

**After programming perform the Front View Camera -Windshield Learn procedure as found in SI.**

#### Version History

<b>Version</b>	<b>4</b>
<b>Modified</b>	<b>10/03/2023 - Created on. 10/04/2023 - Removed statement to learn FVC after programming. 10/14/2024- Updated models. 10/25/24- Added statement to perform FVCM learn after reprogramming to the correction.</b>

GM Global Brands

© 2024 General Motors. All Rights Reserved.