



**Bulletin No.:** PIC6583

**Published date:** 10/25/2024

## Preliminary Information

### PIC6583 U018B set current in one or more modules

#### Models

**Brand:** Cadillac **Model:** Lyriq **Model Years:** 2023 - 2025 **VIN:** All **Engine:** All **Transmissions:** All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	Customer may comment one or more of the following concerns; Service vehicle soon light, Service OnStar message.
<b>Cause</b>	K183 UHF module logic locked

#### Correction:

Perform a global reset by disconnecting 12V battery for 30 minutes, using Document ID: 6307865 Battery Negative Cable Disconnection and Connection.

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
5430912	System Reset	0.5 Hr.

#### Version History

<b>Version</b>	1
<b>Modified</b>	10/25/2024 - Created on.