



Bulletin No.: PIT6271

Published date: N/A

Preliminary Information

PIT6271 Trailer Lighting Inoperative After Accessory Hitch Installed

Models

Brand: **Model:** **Model Years:** **VIN:** **Engine:** **Transmissions:**
from to

Chevrolet Equinox 2025 All All All All

Involved Region or Country:	North America
Condition:	After accessory trailer hitch installation, the trailer lighting is inoperative.
Cause:	The installation instructions are being updated to include the need for the calibration. The instruction sheets will contain the authorization codes.

The accessory trailer hitch kits are currently on stop sale, pending the instruction updates.

This PI will be replaced by a bulletin when the instruction sheets are available.

Version History

Version	1
Modified	10/29/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.