

35-039 Detroit New Final Drive Standard Performance Forward Carrier Change to Top Performance Passive Lube Management

TSB-35-039-FTL

Creation Date:2023-01-26

Engine or Vehicle Affected:

- ▶ Business Class M2
- ▶ 108SD
- ▶ 114SD
- ▶ 122SD and Coronado
- ▶ New Cascadia
- ▶ Cascadia

Note:

REMOVE
INSTALL
CLEAN
REPLACE
F12
F22
F07
F18
F15
F25
F16
F26
F35
F36
F03
F14
F23
F24

CONTACT INFORMATION

For questions, please create a Service Technical Request using the DTTS Application on the DTNA Portal.

Document Number:0000096679