

Subject

Oil Leak from the Engine Oil Level Sensor Area

Market

USA

Service Category

Engine/Hybrid System

Section

Engine Mechanical

Applicability

RAV4, Camry, RAV4 HV, Camry HV

APPLICABLE VEHICLES

2022-2024	RAV4	2022-2024	Camry
2022-2024	RAV4 HV	2022-2024	Camry HV

CONDITION

Some technicians may report an engine oil leak from the Engine Oil Level Sensor area (Fig. 1-3).




Fig. 1




Fig. 2



Fig. 3

RECOMMENDATIONS

If a vehicle is experiencing an oil leak anywhere around the Oil Level Sensor, please do the following:

1. Take clear pictures of the origin of the leak.
2. Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references