



Bulletin No.: PIP6026

Published date: 12/3/2024

Preliminary Information

PIP6026 Information Needed When Creating Technical Assistance Case for concerns on DCT Transmissions

Models

Brand: Chevrolet **Model:** Corvette **Model Years:** 2020 - 2025 **VIN:** All **Engine:** All All **Transmissions:** M1L M1M MLH

Involved Region or Country:	North America
Condition:	During diagnostics it may be required to start a Technical Assistance case for transmission performance and/or leak concerns.
Cause	Additional Information needed.

Correction:

NOTE: Prior to getting the session log of the vehicle wide DTC's Please do NOT clear any DTC'S This data is needed to ensure accurate diagnostics.

During Transmission Diagnostics it may become necessary to start a Technical Assistance Case.

In order to provide the best diagnostic experience additional information is now required.

Prior to starting a Technical Assistance Case please obtain a picture of the Transmission Unique Number (TUN) off the side of the transmission, or if unable to get a picture of the TUN number on the side remove the air box and get a picture of the TUN on top of the transmission.

Also, please perform a vehicle wide DTC scan and upload the session and the picture to the case using Dealer Case Management, For US Dealer please Refer to [PIP5632H](#).

For Canadian Dealers after obtaining the picture and the session log please email them following the process in [PIP4902R](#).

This information will be critical in providing a timely response without the need to request additional information.

Also, if a case is started for a leak concern Pictures of the leak test with the leak trace powder applied must be attached to the case.

Pictures of the leak test with the leak test powder should also be included in the warranty claim as well.

NOTE: Failure to include the pictures with the warranty claim WILL result in a debit of the entire repair to the dealer.

Version History

Version	1
Modified	12/03/2024 - Created on.