



STAR ONLINE PUBLICATION



Case Number: S2418000016

Release Date: December 2024

Symptom/Vehicle Issue: MIL-On/Check Engine Lamp On

Customer Complaint/Technician Observation: The customer's complaint may include a MIL-On/Check Engine Lamp On condition. The customer may also complain of a Limp-In condition that occurred on the same key cycle as the MIL-On. Upon further investigation, the technician may find a DTC set for P0606-00-ECU Internal Performance set in ECU1 (Engine Control Unit 1).

Discussion: If the above conditions exist, replacing any components will likely not repair the issue. The issue is under engineering investigation at this time. Erase the DTC and return the vehicle to the customer.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found