

Volvo Car USA LLC

Technical Journal

Technical Journal Title TPMS Service Required		Ref. No. TJ 37137.1.0	
Issuer (Dept.) Technical Service		Issue Date 10/22/24	Status Date 10/31/24
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3674	
Function Description Tire pressure monitoring control system		Page Page 1 of 1	

DESCRIPTION:

If vehicle has message "TPMS service required" after wheel or TPMS sensor change, follow advice under "Service".

TPMS = Tire Pressure monitoring System

CSC Customer Symptom Codes

Code	Description
LI	Warning lights and chimes/Tire pressure monitoring, Service required warning

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
356							2025-9999		-	202442-999952

SERVICE:

To be able to program the TPMS sensors, download Software Product 32425172 then follow the script to learn sensors on respective position.

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
99922-2	General Reimbursement acc to. TJ

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3674.