

## Volvo Car USA LLC

## Technical Journal

Technical Journal Title Door Stop noise		Ref. No. TJ 37085.1.0	
Issuer (Dept.) Technical Service		Issue Date 10/22/24	Status Date 10/31/24
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 8315	
Function Description Door stop		Page Page 1 of 3	

### Attachment

File Name	File Size
TJ 37085.jpg	0.0194 MB

### DESCRIPTION:

If customer complains of noise when opening/closing the door or if the door stop is loose, please follow advice under "Service".

### CSC Customer Symptom Codes

Code	Description
F9	Doors/Squeak/rattle/When opening/closing
G8	Doors/Squeak/rattle/Front side door
G9	Doors/Squeak/rattle/Rear side door

### DTC Diagnostic Trouble Codes

### Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
416							2024-2025		-	202336-202426

### SERVICE:

Follow instructions below:

1. Use a torque wrench, set at 30Nm
2. Open the door
3. Tighten the screw according to the picture

### Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

**Technical Journal 37085.1.0**

---

**VST** Operation Number

<b>VST Operation Number</b>	<b>Description</b>
99921-2	General reimbursement acc. to TJ

**VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8315.

**To view TJ attachment continue to next page. This TJ has one attachment.**

