

<b>REFERENCE:</b>	<b>TSB:</b> 08-250-24 <b>GROUP:</b> 08 - Electrical	<b>Date:</b>	December 7, 2024	<b>REVISION:</b>	-
<b>VEHICLES AFFECTED:</b>	<b>2023 (WL) Jeep Grand Cherokee / Grand Cherokee L</b> This bulletin applies to vehicles equipped with a 7 and 4 Pin Wiring Harness (Sales Code XF2).	<b>MARKET APPLICABILITY:</b>			
		<input checked="" type="checkbox"/> NA		<input checked="" type="checkbox"/> MEA	
		<input checked="" type="checkbox"/> SA		<input checked="" type="checkbox"/> IAP	
		<input checked="" type="checkbox"/> EE		<input checked="" type="checkbox"/> CH	
<b>CUSTOMER SYMPTOM:</b>	<p>Customers may experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle may exhibit/set the following Diagnostic Trouble Code (DTC):</p> <ul style="list-style-type: none"> <li>● C2214-00 - ITBM Not Calibrated.</li> </ul> <p>Customers may also comment on the following:</p> <ul style="list-style-type: none"> <li>● Trailer lights are not working correctly when a trailer is plugged in after an aftermarket installation.</li> </ul>				
<b>CAUSE:</b>	<b>PROXI configuration</b>				

**DISCUSSION:**

Vehicles may exhibit trailer lights not operating properly after an aftermarket installation and relevant DTCs upon connecting to a trailer due to an incorrect PROXI configuration. Performing the PROXI configuration alignment routine should resolve these concerns.

**POLICY:**

Information only.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*