



**Bulletin No.:** PIT6274A  
**Published date:** 12/5/2024

## Preliminary Information

### PIT6274A Error Message Referring To Vision Camera System With DTC B1C48

#### Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet Blazer EV	2025		All All	All	
Chevrolet Equinox EV	2025		All All	All	

<b>Involved Region or Country</b>	United States, Canada, Mexico and Europe
<b>Additional Options (RPO)</b>	UCV
<b>Condition</b>	Some customers may comment seeing a popup stating Vision/Camera system.
<b>Cause</b>	This is due to a software anomaly.

#### Correction:

Do not replace any parts at this time.

Engineering is aware of the concern.

The PI will be updated when a repair is available.

Until a fix is available, the concern can not be corrected by clearing codes.


#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3486358	Verify Current DTC B1C48 And Unable To Clear	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

#### Version History

<b>Version</b>	<b>2</b>
<b>Modified</b>	<b>11/04/2024 - Created on.</b> <b>12/05/2024 - Updated Labor Operation.</b>

 GM Global Brands

© 2024 General Motors. All Rights Reserved.