



Bulletin No.: PIT6250A
Published date: 12/5/2024

Preliminary Information

PIT6250A Diagnostic Tip: Steering Wheel Rubbing On Upper Trim Cover

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Silverado EV	RST 2024 - 2025	All	All	All
GMC	Sierra Denali EV	2024 - 2025	All	All	All

Involved Region or Country	North America
Condition	A customer/driver could notice that the steering wheel is making contact with the steering column trim cover and causing a noise.
Cause	The lower steering column trim cover could be causing a misalignment with the upper trim cover

Correction:

To correct the concern, replace the lower steering column trim cover.

Then inspect the upper steering column trim cover to see if it is scratched (See Example Below) If the upper steering column trim cover is scratched, it will also have to be replaced.



Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
7440150	Steering Wheel Shroud Replacement	Use Published Labor Time

Version History

Version	2
Modified	10/04/2024 - Created on. 12/5/2024- Updated model years