



SSM 53201 2023-2024 F-Super Duty - Turn Signal Fast Flash Due To Upfitter Lighting Modifications

Some 2023-2024 F-Super Duty vehicles may exhibit a turn signal fast flashing condition as a result of vehicle lighting modification performed during the upfitting process. To correct the condition, refer to the applicable version of the Ford Super Duty Body Builder Layout Book (BBLB) for steps regarding configuration of the exterior lighting due to upfitter. The BBLB can be found at <https://www.fordpro.com/en-us/upfit/bbas> under publications tab. In the BBLB, refer to electrical section for instructions using the latest software level of the Ford Diagnosis and Repair System (FDRS) scan tool. Changes to the lighting configuration because of upfit modifications are non-warrantable.