



Bulletin No.: PIP6028

Published date: 12/9/2024

Preliminary Information

PIP6028 Diagnostic Aid: Unable to Remove Transmission Fill Cap

Models

Brand:	Model:	Model Years:	VIN:	Engine:	Transmissions:
Chevrolet	Equinox	2025	from to	All All	MRQ

Involved Region or Country	North America
Condition	Unable to remove the transmission fill cap.
Cause	Incorrectly positioned ground cable.

Correction:

Technicians may find when completing service or adding transmission fluid to the vehicle they cannot remove the transmission fill cap.

They may find the engine ground cable incorrectly positioned blocking access to the fill cap.

Incorrectly oriented ground cable.



If this condition is found remove the bolt holding the ground strap and relocate the strap to the position shown below and tighten the bolt down to 80 lb in (9Nm).


Correct orientation of the engine wiring harness ground cable.



Reorienting the ground cable will allow the fluid fill cap to be removed and installed.

Version History

Version	1
Modified	12/09/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.