



Bulletin No.: PIT6301

Published date: 12/13/2024

Preliminary Information

PIT6301 GM Accessory Illuminated Sill Plates Inoperative and /or GM Accessory Keyless Entry Keypad Inoperative

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Cadillac	Escalade	2025	All All	All	All
Cadillac	Escalade ESV	2025	All All	All	All
Chevrolet	Suburban	2025	All All	All	All
Chevrolet	Tahoe	2025	All All	All	All
GMC	Yukon	2025	All All	All	All
GMC	Yukon XL	2025	All All	All	All


Involved Region or Country	North America
Additional Options (RPO)	Dealer installed illuminated door sill plates or Dealer installed keyless entry keypad
Condition	<p>This PI addresses two different issues:</p> <ol style="list-style-type: none"> 1. Some dealerships may comment that after installing the GM accessory illuminated door sill plate kit that they are inoperative. 2. Some dealerships may comment that after installing the GM accessory keyless entry keypad that it is inoperative or unable to program.
Cause	The cause of either of these concerns is that the BCM programming is not currently available.

Correction:

GM Engineering is aware of these issues and working on releasing new BCM calcs to correct these concerns. At this time, no further repairs should be performed and when the new calcs are available this PI will be updated.

Version History

Version	1
Modified	12/13/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.