



TECHNICAL SERVICE BULLETIN

Luggage Compartment Scuff Plate To Luggage Compartment Side Trim Panel Gap

24-2422

11 December
2024

Model:

Ford 2024 Mustang

Markets: North American markets only

Issue: Some 2024 Mustang vehicles may exhibit the luggage compartment scuff plate with a gap near the right or left luggage compartment side trim panel. This may be due to the luggage compartment scuff plate installation. To correct the condition, follow the Service Procedure to replace the luggage compartment scuff plate.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2024 Mustang
- Gap between the luggage compartment scuff plate and the luggage compartment side trim panel

Parts

Service Part Number	Claim Quantity	Package Order Quantity	Number in Package	Description
PR3Z-6340374-AB	1	1	1	Luggage Compartment Scuff Plate

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Service Part Warranty (SPW)/Service Part New Vehicle (SPNV)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/SPW/SPNV/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2024 Mustang: Inspect And Replace The Luggage Compartment Scuff Plate (Do Not Use With Any Other Labor Operations)	242422A	0.3 Hrs.

Repair/Claim Coding

Causal Part:	6340374
Condition Code:	34

Service Procedure

1. Does the luggage compartment scuff plate to luggage compartment side trim exhibit a gap similar to Figures 1-2? (Right side shown in figure 2, Left side similar)

Figure 1




Figure 2



- (1). Yes - proceed to Step 2.
- (2). No - this article does not apply.

2. Remove the luggage compartment scuff plate by unscrewing the thumb nut type retainers. (Figure 3)

Figure 3



E188147

3. Install the new luggage compartment scuff plate.

© 2024 Ford Motor Company
All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.