

SERVICE BULLETIN 622 – FUEL LEVEL SENDER

| Subject: Fuel Level Sender Replacement | | | |
|--|---------------------------|-------------------------------|------------------|
| Bulletin Number | Models Affected | VIN Range | Markets Affected |
| 622 | Tiger 1200 GT Pro | From VIN BP6056 to VIN CA4627 | All Markets |
| | Tiger 1200 Rally Pro | From VIN BP6056 to VIN CA4302 | |
| | Tiger 1200 GT Explorer | From VIN BP6056 to VIN CA3861 | |
| | Tiger 1200 Rally Explorer | From VIN BP6056 to VIN CA4331 | |

Dealers are requested to replace the fuel level sender on the above models as outlined in Service Bulletin 622, found in the Technical Information section of TriumphOnline.net

Reminder: use the "[VIN Enquiry](#)." function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, or a Triumph owner visits your dealership.

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.