



Service Bulletin

Bulletin No.: PIE0787B

Date: November, 2024

ENGINEERING INFORMATION

Subject: Engineering Information - Diesel Fuel Leak at the Fuel Filter Assembly

This PI has been revised to end the need for gathering information from the field. Please discard PIE0787A.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models		2024				
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A / D)	2022	2022			Equipped with 3.0L (RPO LM2)	
	Silverado 1500	2023	2024			Equipped with 3.0L (RPO LZ0)	
	Silverado 2500 HD / 3500 HD	2022				Equipped with 6.6L (RPO L5P)	
	Suburban					Equipped with 3.0L (RPO LM2)	—
	Tahoe						
GMC	Sierra 1500 New (RPO J22, VIN Digit 5 = H / U)		2022				
	Sierra 1500	2023	2024			Equipped with 3.0L (RPO LZ0)	
	Sierra 2500 HD / 3500 HD	2022				Equipped with 6.6L (RPO L5P)	
	Yukon Models					Equipped with 3.0L (RPO LM2)	

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	3
Modified	Released April 25, 2024 Revised August 27, 2024 - Update the Subject, Correction and Warranty Information. Revised November 18, 2025 - Ended the need for gathering further information from the field.

