

GPOP - Issue Review System

Part Number: 05281614A\$, 68570195A\$, 68604560A\$

Part Description: Turbocharger Kit

Issue Description: Please note many parts of the Turbo Assembly can be serviced separately and complete turbo replacement may not be necessary. If the Turbo is being replaced for a noise or a rattle, inspect the wastegate for binding. The actuator kit is serviced separately. If the turbo is being replaced for an oil leak concern, please inspect the area around the turbo oil feed o-ring for a leak. The o-ring is serviced separately.