



Bulletin No.: PIT6306

Published date: 12/16/2024

Preliminary Information

PIT6306 Diagnostic Tip - Service Door Message

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Cadillac Escalade		2025	All All	All	All
Cadillac Escalade ESV		2025	All All	All	All
Cadillac Escalade IQ		2025	All All	All	All

Involved Region or Country	North America
Additional Options (RPO)	APD
Condition	A customer may comment that they have a “Service Left Front, Right Front, Left Rear or Right Rear Door” DIC message along with a “Door Open” warning immediately after closing any door regardless of power door setting.
Cause	Software anomaly.




Correction:

Engineering is aware of this potential condition and working on a repair. Until a repair is available, the messages can be cleared by opening and closing the door indicated by the DIC message. No further repairs should be performed.

Version History

Version	1
Modified	12/16/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.