



STAR ONLINE PUBLICATION



Case Number: S2408000127

Release Date: December 2024

Symptom/Vehicle Issue: Instrument Panel Cluster (IPC) Sets Diagnostic Trouble Code (DTC) U0158-00 Lost Communication With the HUD Heads Up Display

Technician Observation: Technician observed the IPC had DTC U0158 active while the vehicle was still in logistic/shipping mode and once the vehicle was removed from logistic/shipping mode the DTC went to stored.

Discussion: If during the vehicle preparations and removal of the vehicle from logistics/shipping mode the IPC sets DTC U0158, clear the DTC to repair, do not replace any parts. This DTC that may set within the IPC, it **does not create** a component functional issue and or a customer related impact. Updates to resolve the erroneous DTC, are expected within the 2nd quarter of 2025.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found



STAR ONLINE PUBLICATION



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found