

WORK DESCRIPTION FOR FIELD MEASURE

Code: 24P5496444

Version: 2.0

Update AIRMATIC control unit software

Model 296

- i** • Always use the **latest** XENTRY Diagnosis software release with all available add-ons.
- Make sure to follow the operation steps exactly as described in XENTRY Diagnosis!
- Use a battery charger to ensure sufficient power supply **of the vehicle on-board electrical system battery** (greater than 12.5 V).
- If XENTRY Diagnosis is already connected to the vehicle, start with **Work Procedure step 2**.
 - i** If two or more software updates or SCN codings are performed during one workshop or SCN coding operations are performed, operation items 02-4762 and 02-5058 must **only be invoiced once for each workshop order!**

Work Procedure

1. Connect XENTRY Diagnosis.
2. Update **AIRMATIC** control unit software.
 - i** To do this, select menu item "Quick test view → N 51/8-AIRMATIC → Adaptations → Control unit update → Update of control unit software".
 - i** Then follow the user guidance in XENTRY Diagnosis.
3. Disconnect XENTRY Diagnosis.

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-9334	Update AIRMATIC control unit software (with XENTRY Diagnosis connected)	0.1 h	54 964 44
02-4762*	Connect/disconnect diagnostic system (XENTRY Diagnosis)	0.1 h	54 964 44
02-5058*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1 h	54 964 44

* Operation item must be invoiced only once for each workshop order!