



## **SSM 53238 2021-2024 Bronco - Turn Signal Flashes Briefly In The Opposite Direction After A Turn Is Completed**

Some 2021-2024 Bronco vehicles may exhibit the opposite turn signal direction flashing briefly once a turn is completed. This may be due to the steering column multifunction switch. To correct the concern, replace the steering column multifunction switch. Refer to the Workshop Manual (WSM), Section 211-05. For claiming, use causal part 13K359 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual. If labor times are not available, claim M-time.