



STAR ONLINE PUBLICATION



Case Number: S2408000128

Release Date: December 2024

Symptom/Vehicle Issue: Vehicle Does Not Start When Depressing the Keyless-Go Button

Customer Complaint/Technician Observation: The owner complains that the vehicle is not starting when pressing the Keyless Ignition Node (KIN). The technician observed Radio Frequency Hub (RFHUB) has set either B1A7D-09 Start Button- Component Failure or B1A7D-01-Start Button - General Electrical Failure

Repair Procedure: If the RFHUB has set Diagnostic Trouble Codes (DTCs) within the RFHUB proceed with the following.

If the DTC is stored, reset the RFHUB to complete, no parts replacement required.

If the DTC is active, follow the normal diagnostics as detailed in Service Library (SL) for the respective DTC to complete.

Note: Inspecting and *testing* the wiring for continuity, shorts and terminal pin fit as needed. Usually DTCs that go stored for a component fault do not require a component replacement.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found