



**Bulletin No.:** PIT6310

**Published date:** 12/19/2024

## Preliminary Information

### PIT6310 Rear Tail / Stop / Turn Signal Lamps Intermittently Inoperative

#### Product Investigation Review Required

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Chevrolet	Suburban	2025	All All All	All	All
Chevrolet	Tahoe	2025	All All All	All	All
GMC	Yukon	2025	All All All	All	All
GMC	Yukon XL	2025	All All All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	<b>A customer may comment that one or both rear tail lamps do not illuminate intermittently. All tail lamp functions may be inoperative or only a portion such as a stop lamp, park lamp and/or turn signals. A customer may also comment that they experience a turn signal that flashes fast.</b>
<b>Cause</b>	<b>The cause of this condition could be an internal fault with the tail lamp assembly.</b>

#### Correction:

If after performing normal SI Diagnostics and a root cause is not found, then replace the affected tail lamp assembly.

**IMPORTANT: After replacing a tail lamp assembly, confirm the new service part does not have the same condition by operating all the tail lamps and hazard flashers for several minutes.**

#### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage.


<b>Labor Operation</b>	<b>Description</b>	<b>Labor Time</b>
<b>2041150</b>	<b>Rear Body Structure Stop Lamp Replacement</b>	<b>Use Published Time</b>

### **Additional SI Keywords**

light lights lighting passenger driver side left right

### **Version History**

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>12/19/2024 - Created on.</b>

 GM Global Brands

© 2025 General Motors. All Rights Reserved.