



**Bulletin No.:** PIP6034

**Published date:** 12/19/2024

## Preliminary Information

### PIP6034 DTCs P2148 P2151 P2154 P2157 Failed As Current Or History

#### Proactive

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Buick	Enclave	2025	All	All 2.5 LK0	All
Chevrolet	Traverse (All New)	2024 - 2025	All	All 2.5 LK0	All
GMC	Acadia	2024 - 2025	All	All 2.5 LK0	All

<b>Involved Region or Country:</b>	<b>North America</b>
<b>Condition:</b>	<b>DTC's P2148, P2151, P2154, P2157 failed as current or in history.</b>
<b>Cause:</b>	<b>Internal PCM hardware issue.</b>

#### Correction

If you encounter one of these vehicles that have one or more of the following DTC's P2148, P2151, P2154, P2157 set as current or in history.

Replace the PCM using the latest parts available in EPC.

#### Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>12/19/2024 - Created on.</b>

 GM Global Brands

© 2025 General Motors. All Rights Reserved.