

## GPOP - Issue Review System

**Part Number:** 68516699A\$, 68516705A\$, 68516708A\$, 68516709A\$, 68516710A\$,  
68516711A\$, 68516712A\$

**Part Description:** EXHAUST - MUFFLER AND TAILPIPE

---

**Issue Description:** For Exhaust noise squeak during startup acceleration deceleration please do following:  
1. DO NOT remove actuators 2. Verify noise by cycling EEV manually via WiTech 3. Verify noise with test drive (optional) 4. If the noise is confirmed, replace the system without removing the actuators.