

REFERENCE:	TSB: 17-001-25 GROUP: 17 - Rear Suspension	Date:	January 4, 2025	REVISION:	17-002-24
VEHICLES AFFECTED:	<p>2023 - **2024** (GC) Alfa Romeo Tonale 2023 - **2024** (GG) Dodge Hornet</p> <p>This bulletin applies to vehicles built on or after July 13, 2023 (MDH 0713XX) and on or before July 26, 2023 (MDH 0726XX) equipped with the 2.0L I4 DOHC DI Turbo w/ESS Engine (Sales Code EC1).</p>	MARKET APPLICABILITY:			
CUSTOMER SYMPTOM:	<p>The customer may notice one or more of the following:</p> <ul style="list-style-type: none"> • Paint peels off very easily on rear suspension springs Fig. 1. • Degradation of suspension performance. 				
CAUSE:	Paint falling off				

This bulletin supersedes Technical Service Bulletin (TSB) 17-002-24, date of issue May 24, 2024, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include an additional model year, updated Skill Category and Diagnosis statement.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 24-088, date of issue May 24, 2024. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.



Fig. 1
Paint Missing

REPAIR SUMMARY:

This bulletin involves replacing both rear suspension springs.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
02-30-01-9E	Spring, Rear Coil - Replace Both Sides Includes Wheel Alignment (1 - Semi-Skilled)	**17 - Rear Suspension**	2.5 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
2	68632844AA	Spring, Suspension Rear	
6	K06511501AA	Bolt, Torx Head	
2	K06511458AA	Nut, Hex Flange Lock	
2	68254480AA	Rear strut to rear knuckle bolts	
2	06511458AA	Rear strut to rear knuckle nuts	
1	68631072AA	Upper rear stabilizer bar nuts	

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
Spring Compressor	1874555001	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the Repair Procedure. If any vehicle not on the VIN list exhibits the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Replace the rear suspension springs. Refer to the detailed service procedures listed in DealerCONNECT>Service Library>Service info>under: 17 - Rear Suspension / Strut, Rear / Disassembly and Assembly.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.