

DIAGNOSTIC TROUBLE CODE (DTC) P2270-00 STORED IN THE POWERTRAIN CONTROL MODULE (PCM)- P6 ONLY

Customer Voice:

- Malfunction indicator lamp is displayed.

Technical Description:

- Engineering investigations have found that a number of vehicles have DTC P2270-00 'O2 Sensor Signal Stuck Lean - Bank 1, Sensor 2' stored in the PCM. During diagnosis the technician has determined that the mid catalyst heated oxygen sensor (HO2S) is at fault leading to a replacement sensor being installed

Status:

- Where the DTC P2270-00 is found to be stored in the PCM, follow the DTC helptext to diagnose the issue. If following diagnosis it is determined that a mid catalyst HO2S is required raise a TA before proceeding with the repair. The TA team will provide guidance on how to progress.
- Do not replace any components unless advised by the Technical Assistance (TA) team.

Refer to SSM 76223

Defender

- 20MY+ Defender

