

WINDSHIELD MOULDINGS DAMAGED DURING REMOVAL AND / OR INSTALLATION

Customer Voice:

- The windshield trim is not sitting correctly or rattles.

Technical Description:

- During removal or installation of the exterior A-pillar trim, the correct procedures are not being followed resulting in damage to the trim.

Status:

- SSM76227 has been published to request reminding technicians of the Workshop Manual procedure and to inspect the trim for damage due to incorrect removal or installation process.

Defender

- 20 - 25MY Defender

