

Reference	SSM76228
Models	Defender / L663 Discovery / L462 New Range Rover / L460 New Range Rover Sport / L461
Title	Oil leak from the transfer case
Category	Driveline
Last modified	10-Dec-2024 00:00:00
Symptom	508000 Transfer Case Concerns

Content	<p>Model / Model Year / Derivative Range Rover Sport / 23-24MY / All Range Rover / 22-24MY / All Defender / 22-24MY / All Discovery / 21-24MY / All</p> <p>Situation: JLR Engineering investigations have found reports of oil leaks from the transfer case.</p> <p>Cause: Damage to the front input shaft seal and/or rear output shaft seal.</p> <p>Action: Refer to the service request below.</p> <p>Service Request: If you have an oil leak from the front input shaft seal and/or rear output shaft seal, then do not repair the vehicle, do not clean any oil from the transfer case, hold the vehicle and raise a Technical Assistance (TA) to PTS_800. Attach photos to the TA to show the transfer case oil leak.</p> <p>The PTS_800 engineering team will provide further guidance, and may initiate a Parts Return Request (PRR) in order to complete engineering analysis on the transfer case. For this reason it is important that the oil within the transfer case and the seals are not removed or disturbed.</p> <p>(Ref 000390661) (Ref 000379707)</p>
----------------	---