

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

McLaren 720S and 750S Lower Bodyside Not Flush

Document Information

Location: Body Panels & Closures

Topic: New repair instructions in the McLaren Service Portal for when the lower bodyside does not sit flush

Condition: Lower body panel not flush or bulging out

Diagnostic Trouble Codes: N/A

Measure

If there is a concern raised of the lower bodyside not fitting flush (bulging out), please refer to the new repair instructions in the McLaren Service Portal.

The instructions can be found under Rework Bodyside Lower Panel in the McLaren Service Portal.

These have new torque values and instructions on how to rectify and resolve this issue.



Parts Information

N/A

Attachments

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.