

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

McLaren 750s New Service Portal Instructions for Door Stoneguard Rework

Document Information

Location: Body Panels & Closures

Topic: New instructions for reworking door stoneguards

Condition: N/A

Diagnostic Trouble Codes: N/A

Measure

McLaren Automotive has created a new McLaren Service Portal (MSP) work instruction D052797 - 750S Rework Door Stoneguard.

This rework is to resolve complaints of door clicking for the 750S Coupe and Spider.

Care Point: Always refer to the McLaren Service Portal to follow the latest work instructions available.

Parts Information

N/A

Attachments

N/A

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.