



Technical Service Bulletin

93 PSS: Warning message: "Electrical system: fault. Please contact workshop" (e-tron GT)

93 24 42 2075720/2 December 12, 2024. Supersedes Technical Service Bulletin Group 93 number 24-24 dated October 22, 2024 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2024 – 2025	All	Not Applicable

Condition

This bulletin applies to MY24-25 e-tron GT vehicles only.

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Service</i> (Updated Solution ETA)
1	10/22/2024	Initial publication

Customer states:

After switching on the ignition (terminal 15), a yellow warning lamp appears in the instrument cluster with the message: "Electrical system: fault. Please contact workshop". The vehicle cannot be driven in this condition. After switching the ignition off and on, the message is no longer shown, and the vehicle can be driven again without any restrictions.

Workshop findings:

No relevant DTCs are stored.

Technical Background 1

Certain usage behavior of the customer can lead to a (temporary) restriction to the function in a specific use case.

Production Solution

Improved software planned in production Q3/2025.

Service

1. Explain to the customer that a solution is expected to be available by the end of the 1st quarter of 2025 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*).



Technical Service Bulletin

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2075720**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.