

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title Parking climate timer intermittently not active		Ref. No. TJ 37131.2.0	
Issuer (Dept.) Technical Service		Issue Date 12/10/24	Status Date 12/17/24
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 8763	
Function Description Timer		Page Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*Updated Service information, Vehicle Type, Warranty claim info and VST Operation No.

If customer complains that the pre-set timers are not executed when using either the Volvo Car mobile app or via CSD, follow advice under "Service".

CSD = Center Screen Display

CSC Customer Symptom Codes

Code	Description
TN	Temperature control/Heater does not work

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
356							2025-2025		-	202417-202447

SERVICE:

*A software solution is introduced from version 1.1.21. Please perform a software upgrade according to TJ 31543.

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

Technical Journal 37131.2.0

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8763.