

# V O L V O

## Volvo Car USA LLC

## Technical Journal

Technical Journal Title TPMS Service Required		Ref. No. TJ 37137.2.0	
Issuer (Dept.) Technical Service		Issue Date 12/10/24	Status Date 12/17/24
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3674	
Function Description Tire pressure monitoring control system		Page Page 1 of 1	

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

### DESCRIPTION:

\* Service, Vehicle type and VST Op number updated

If vehicle has message "TPMS service required" after wheel or TPMS sensor change, follow advice under "Service"

TPMS = Tire Pressure monitoring System

### CSC Customer Symptom Codes

Code	Description
LI	Warning lights and chimes/Tire pressure monitoring, Service required warning

### DTC Diagnostic Trouble Codes

### Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
356							2025-2025		-	202442-202448

### SERVICE:

\*A software solution is introduced from version 1.1.22, perform a software upgrade according to TJ 31543.

\*The tire pressure monitoring system can only provide updated information after you have driven the car above 30 km/h (20 mph) for several minutes.

### Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

## Technical Journal 37137.2.0

---

### VST Operation Number

VST Operation Number	Description
36004-2	Software Control Module downloading

### VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3674.