

Technical Journal

TITLE:

AC Compressor drilling noise

REF NO: TJ 37104.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515 Polestar		ISSUE DATE: 2024-10-22	STATUS DATE: 2024-12-16
FUNC GROUP: 8730	FUNC DESC: Climate unit	Page 1 of 2	

Attachment

File Name	File Size
TJ_37104_1.MOV	8.2323 MB

DESCRIPTION:

If there is a drilling noise from the AC Compressor (see attachment TJ_37104_1.MOV), please follow advice under Service.

CSC Customer Symptom Codes

Code	Description
D5	Climate control system/Unusual noise

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534							2021-2025		-	202007-202446

SERVICE:

Proceed with replacement of the AC compressor bracket spring kit according to VIDA (VCC-530001-2).

This TJ applies only for vehicles with Variant code EP02.

Technical Journal 37104.1.0

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
87401-2	Spring kit, A/C compressor bracket

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report Polestar” and sub concern area “Support not needed Polestar”, use function group 8730.

This TJ has one video attachment.