

Technical Journal

TITLE:

TPMS Service Required

REF NO: TJ 37133.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515 Polestar		ISSUE DATE: 2024-12-10	STATUS DATE: 2024-12-23
FUNC GROUP: 3674	FUNC DESC: Tire pressure monitoring control system	Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*Service and vehicle type is updated

If vehicle has message "TPMS service required" after wheel or TPMS sensor change, follow advice under "Service"

TPMS = Tire Pressure monitoring System

CSC Customer Symptom Codes

Code	Description
LI	Warning lights and chimes/Tire pressure monitoring, Service required warning

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
359							2025-2025		-	202402-202446

SERVICE:

A software solution is introduced from version 1.1.21, perform a software upgrade according to TJ 35361.

*The tire pressure monitoring system can only provide updated information after you have driven the car above 30 km/h (20 mph) for several minutes.

Technical Journal 37133.2.0

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

LABOR TIME:

Labor time subject to change without notice.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support not needed Polestar", use function group 3674.