

# WRU7 Workshop campaign - Replace tailpipe covers

---

## WRU7 Workshop campaign - Replace tailpipe covers

ID Number	WRU7
Model(s)	911 (992)
Model Year(s)	2025 - 2026
VIN List	Attached
Number of Affected VINs	23
Issue Description	During ongoing quality analyses, it was determined that exclusive tailpipe covers were installed on the affected vehicles that do not meet the required specifications. The long-term quality of the rear apron air intake frame cannot be permanently guaranteed over the service life of the vehicle and under high thermal loads, for example during longer high-speed rides. Customers might consider this as a visual detriment. For this reason, the Exclusive tailpipe covers must be temporarily replaced with sports tailpipe covers until an optimized component status is available.
What Dealers Should Do	Please arrange for this action to be carried out on the affected vehicles before handing the vehicles over to customers.  <b>At the time of this posting (12/12/24) repair is immediately available</b>
TI	<a href="#">No. 207-24</a>

### Required parts

The required parts for carrying out the campaign can be found in the respective Technical Information (TI), "Warranty Processing" section.

#### Ordering required parts

Please initially order only 80% of the parts you need.

Parts requirements exceeding 80% of the required quantity, if needed, must be ordered separately by GIM markets and non-GIM markets.

Non-GIM markets

Parts can be ordered immediately

GIM markets

Parts stocked automatically (for max. 80% of the total quantity required)

## Warranty processing

### Validity:

This workshop campaign will be carried out up to 05.12.2029 and will be closed by the specified date. Please note that warranty claims can only be processed up to this date.

### Scope 1: Replace tailpipe covers

- Vehicle has not yet been delivered to customer

Damage Code	WRU7 66 000
Repair Code	2
Labor time	250 TU

### Scope 2: Replace tailpipe covers

- Vehicle has already been delivered to customer

Damage Code	WRU7 66 000
Repair Code	2
Labour time	266 time units

Please enter the campaign that was carried out for vehicles that have already been delivered in the Warranty and Maintenance logbook.

## Customer mobility

If requested, mobility for the affected customer can be guaranteed by offering a suitable replacement vehicle. Please invoice this additional service via WWS with the campaign scope.

---

### Attachments

1. [WRU7 Workshop Campaign VIN List V2 12.12.2024 HT.xlsx](#)