

WRU2 Workshop campaign – Replacing Over-the-Air (OTA) control unit

WRU2 Workshop campaign - Replacing Over-the-Air (OTA) control unit

ID Number	WRU2
Model(s)	Taycan (Y1A/Y1B/Y1C)
Model Year(s)	2025
VIN List	Attached
Number of Affected VINs	168
Issue Description	<p>It is possible that the boot loader programmed on the over-the-air (OTA) control unit does not meet the required specifications in the affected vehicles.</p> <p>As a result, Porsche Connect services / online services and the eCall system are not available. Lack of connectivity is indicated by a red LED in the roof console.</p> <p>To prevent this from happening, the over-the-air control unit must be replaced in the affected vehicles.</p>
What Dealers Should Do	<p>Please arrange for this action to be carried out in the affected vehicles during the next workshop visit or before the vehicles are handed over to customers.</p> <p>At the time of this posting (12/13/2024) the repair is available</p>
TI	No. 203/24

Required parts

Part number	Designation	Quantity/vehicle	Parts return*
9J1907018BH	Control unit for online services	1 piece(s)	No

*The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the remanufactured parts process or be scrapped.

Ordering required parts

Please initially order only 80% of the parts you need.

Parts requirements exceeding 80% of the required quantity, if needed, must be ordered separately by GIM markets and non-GIM markets.

Non-GIM markets

Parts can be ordered immediately

GIM markets

Parts stocked automatically (for max. 80% of the total quantity required)

Warranty processing

Validity:

This workshop campaign will be carried out up to 05/12/2029 and will be closed by the specified date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code

WRU2 66 000

Repair Code

2

Labor time

90 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [WRU2 Workshop Campaign VIN List V2 12.13.2024 HT.xlsx](#)