

WRS8 Workshop campaign - Rework screw connection for transmission control unit

WRS8 Workshop campaign - Rework screw connection for transmission control unit

ID Number	WRS8
Model(s)	911 GT3 (992) / 911 GT3 Touring (992)
Model Year(s)	2022 - 2023
VIN List	Attached
Number of Affected VINs	10
Issue Description	<p>Due to an incorrect default value in the Workshop Manual, there is the possibility that the screw connections on the transmission control unit carried out as part of the WPJ7 campaign do not meet the intended specifications on the affected vehicles.</p> <p>As a result, it cannot be ensured over the service life of the vehicle that the screw connections on the transmission control unit fulfil the necessary requirements. For this reason, the fastening screws of the transmission control unit must be replaced on the affected vehicles and tightened with the correct tightening torque.</p>
What Dealers Should Do	<p>During the next workshop visit, please arrange for this action to be carried out on the affected vehicles</p> <p>At the time of posting (12/13/2024) repair is available</p>
TI	No. 185/24

Part number	Designation	Quantity/vehicle	Parts return*
PAF009388	Countersunk screw with internal serration, M6 x 25	13 piece(s)	No
9P1321359	Oil pan	1 piece(s)	No
PAF008528	Screw plug with sealing ring M18 x 1.5	1 piece(s)	No

WRS8 Workshop campaign - Rework screw connection for transmission control unit

PAF009391	M6 x 55 Torx screw	20 piece(s)	No
PAF910423	Internal hexagon round-head bolt M6 x 16	5 piece(s)	No

Warranty processing

Validity:

This workshop campaign will be carried out up to 07/11/2029 and will be closed by the specified date. Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code	WRS8 66 000
Repair Code	2
Labour time	232 TU

Please enter the campaign carried out in the Warranty and Maintenance logbook for the vehicle.

Attachments

1. [WRS8 Workshop Campaign VIN List V2 12.13.2024.xlsx](#)