

 HYUNDAI	<h1>Technical Service Bulletin</h1>	Model	Xcient FCEV
		Groups	Body Electrical System[92]
		Classification	Service Action
		Publication number	HCE-24-92-P170-QZ
NOTICE OF REWORK ON WIRING OF STEERING COLUMN FOR HYDROGEN-ELECTRIC TRUCK		Publication date	DEC. 13, 2024

1. DESCRIPTION

This bulletin provides information on how to rework the steering column wiring.

2. EFFECTIVE VEHICLE INFORMATION

- 1) Model : Xcient hydrogen-electric trucks (QZ FCEV)
- 2) Applicable vehicle production date range : From Oct. 29, 2019 to Jun. 11, 2024
- 3) Applicable Vehicle VIN range : From KMFFB18WPLC023493 To KMEKC88Y2RC038147
- 4) Area : U.S.A, Canada, Germany, Switzerland, New Zealand, Israel, Saudi Arabia

3. PARTS INFORMATION

No	PART NAME	PART NUMBER	Q'ty per unit	Remark
1	Rolling Tube	UHM38-20420	1	consigned materials from HMC
2	Strap	91596-7S300 or 7S350	1	
3	Band Cable	91568-3E000	2	

4. OPERATION CODE AND TIME

OP Code	Operation	OP Time	Nature	Cause
40D608R0	Rework the wiring of steering column	1.6 M/H	A32	ZZ3
A32:Parts Apperance problem ZZ3 : Part function defect				

5. SERVICE PROCEDURE

- The external material(PE taping) of the wiring wrapped in the wiring of the steering column shaft is removed and wrapped in a supplied flexible tube(rolling tube) to prevent wiring damage by reducing tension.
- Attachment : Work procedure_adding flexible tube to the wiring of the steering column : 1 copy