



## STAR ONLINE PUBLICATION



**Case Number:** S2508000003

**Release Date:** January 2025

**Symptom/Vehicle Issue:** Auto Door locking Speed Sensing Lock Feature Does Not Lock Doors


**Discussion:** The speed sensing auto door lock feature is not locking the doors upon driving as expected. Use the scan tool to access the Instrument Panel Cluster (IPC), select the MISC folder, select IPC Customer Programmable Features, select speed lock door enable, enable to update.

1C6RRFFG7SN565900


IPC  
Instrument Panel Cluster

Flash DTCs Data Misc Functions System Tests Actuators Details Configuration


NAME  
IPC Customer Programmable Features

 IPC Customer Programmable Features

Please select which programmable features you would like to change below.

 Once complete with programmable features select Done from the drop down menu.

Selected: Speed Unit ▾

 Speed Lock Door Enable

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Center Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.