

Noticeable Play in Height Adjustment of Steering Column

Topic number	LI46.15-P-078766
Version	1
Function group	46.15 - Steering column adjustment
Date	1/8/25
Validity	Model 167, 206, 214, 223, 236, 254, 294, 295, 296, 297, 232, 192, 465, 463
Reason for change	

Complaint

Play noticeable in the height adjustment of the steering column. See arrow direction in attached pictures.

Attachments	
File	Description
Direction of Play.jpg	Direction of height adjustment
	

Cause


Slipped thrust bearing ring on the height adjustment.

Remedy

Install repair kit for height adjustment of the steering column.

For tightening torque, see attachment.

Attachments

File	Description
Adjustment Kit Tightening Torques.JPG 	Tightening Torques

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms						
Chassis/suspension > Steering system > Steering column adjustment > Malfunction						
Chassis/suspension > Steering system > Steering column adjustment > Does not adjust in height						
Chassis/suspension > Steering system > Steering column adjustment > Clattering						
Chassis/suspension > Steering system > Steering column adjustment > Knocks						
Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A2054603803			Repair kit for height adjustment of the steering column	1		X
Operation numbers/damage codes						
Op. no.	Operation text		Time	Damage code	Note	

